







See on our website

- Must be used for tack welding only and remove before completing welding. Avoid exposing the magnets to heat sources of over 80°C for too long.
- \bullet Holding at multiple angles while soldering, brazing, and welding at 45° and 90°
- Fully enclosed for easier cleaning.
- Center hole for easy handling.

2 possible angles: 60° or 90°
Max. Pull Force: 25 kgs
Dimensions: 113x98x19mm