



MAXIMAL
INTENSITY
800A at 35%



MAXIMAL
INTENSITY
700A at 60%



INDICATIVE
UNIT WEIGHT
1600 g



See on our
website

Adhesion force: 136kgs

This 800A magnetic earth clamp allows an easier workstation setup: you only need to place the device on a clean surface, to turn it on and to start welding

- Turn Magswitch on and start welding
- Works instantly
- Connectable everywhere
- Stays clean
- Turn Magswitch off and wipe away the fragments

- Saves the welders time and money
- Quick and easy connection and disconnection
- Easy fastening on flat or rond surfaces