



INDICATIVE
UNIT WEIGHT
1.2 g



See on our
website

Must be used for tack welding only and remove before completing welding. Avoid exposing the magnets to heat sources of over 80°C for too long.

- For professional jobs that demand strong hold down forces. Hold flat and round metal work pieces.
- Two On/Off switches for independent operation
- Turn the magnets Off when setting up, turn On when you're ready to work. Easy and safe set-up!
- Precision machined flat and V-surfaces are ideal for round and square tubing, angle, and flat stock.

- Max. Pull Force : 55kgs

- Dimensions : 152 x 152 x 38 mm