







See on our website

- Must be used for tack welding only and remove before completing welding. Avoid exposing the magnets to heat sources of over 80°C for too long.
- This magnetic square enables the holding of 2 metal work pieces during brazing or welding
- \bullet Holding at multiple angles while soldering, brazing, and welding at 45° and 90°
- Fully enclosed for easier cleaning.
- Center hole for easy handling.

2 possible angles: 45° or 90°
Max. Pull Force: 10 kgs
Dimensions: 113x98x19mm